

Site Photos



Oblique Aerial Photo - north view of the east end of the project area.



Oblique Aerial Photo - north view of the west end of the project area.

Site Photos



Example of new bull rail section and bolt caps beside an old bull rail without a cap that needs replacement.



Looking north across the decking replaced in 2024. Note the acceptable gap width between boards. 1/8 inch is desirable.



Looking west at the transition between the old boardwalk and new boardwalk section replaced in 2024



Example of the new decking with GRK screws



Looking west at the access ramp to Park Sands property. Ramp is included in the scope of work.



Exposed old lag bolt on bull rail that requires replacement.



Existing pathway lighting that needs replacement to provide more light. Fixtures are spaced at approximately 30 ft on one side of the boardwalk.



Electrical conduit and junction box behind light fixture on the south face of the boardwalk.



Small set of stairs leading to the beach. Stairs are included in the scope of work.



Looking east at the edge of the beach facing boardwalk.



East seating area with two sets of stairs included in the scope of work.



West sitting area with one set of stairs and a ramp included in the scope of work.



Small perpendicular section connecting to pathway on the east side of the Beachclub included in the scope of work.



Boardwalk under the west gazebo included in the scope of work.



Connecting Ramp to Pacific Palm **NOT** included in the scope of work.



Small access stairs to be removed and **not replaced**.