

2013 ANNUAL WATER REPORT



May 2014

1.0	INTRODUCTION
2.0	PARKSVILLE WATER SYSTEM
3.0	DISTRIBUTION SYSTEM
4.0	SCADA
5.0	WATER SAMPLING AND TESTING10
6.0	WATER QUALITY COMPLAINTS
7.0	ENGLISHMAN RIVER WATER SERVICE JOINT VENTURE AGREEMENT
8.0	ROUTINE MAINTENANCE PROGRAM
9.0	2013 IMPROVEMENTS
10.0	2013 CAPITAL PROJECTS
11.0	2014 CAPITAL PROJECTS & IMPROVEMENTS
12.0	CROSS CONNECTION
13.0	EMERGENCY RESPONSE PLAN15
APPE	NDIX A - WELL LOCATION MAP
APPE	NDIX B - ARROWSMITH DAM LAKE LEVELS 2013
APPE	NDIX C - MAP OF PRESSURE ZONES
APPE	NDIX D - 2013 BACTERIOLOGICAL TEST RESULTS
APPE	NDIX E - FULL SPECTRUM ANALYSIS
APPE	NDIX F - WATER SYSTEM OPERATING CONDITIONS

1.0 Introduction:

All water suppliers, under their Operating Permit and conditions, are required to provide an annual report to their users with information such as explanation of water source, water test results, maintenance programs and improvements to the water system. The following document summarizes these requirements. City of Parksville operating conditions are shown in Appendix F.

This report has been submitted to Island Health and is posted on the City of Parksville Website. www.Parksville.ca.

2.0 Parksville Water System:

The City of Parksville has approximately 4,500 water connections serving over 11,000 permanent and seasonal residents as well as supplying water to the Regional District of Nanaimo - Nanoose Bay Peninsula system in the summer months.

These users get their drinking water from 3 sources.

- Englishman River Intake
- Springwood Well Field
- Railway Well Field

The water is treated using either liquid or gaseous chlorine and stored in 4 reservoirs at either end of the City.





2.1 Groundwater Wells:

The City's groundwater is pumped from a confined quadra sands aquifer that runs underground alongside the railway tracks from Trill Drive to the City's boundary in the southwest. The City currently has 18 production wells ranging from 0.9 l/s (12 IGPM) to 10.3 l/s (136 IGPM). See **Appendix A** for Well locations.

Well Name	Well Depth (m)	Production (l/s, Igpm)
Springwood Well #1	31.9	2.2, 29
Springwood Well #2	10.4	Off Line
Springwood Well #3	25.3	3.5, 46.2
Springwood Well #4	9.8	Off Line
Springwood Well #5	31.0	5.3, 70
Springwood Well #6	31.1	3.2, 42.2
Springwood Well #7	40.2	3.2, 42.2
Springwood Well #8	39.4	8.5, 112
Springwood Well #10	25.6	4.5, 59.4
Springwood Well #11	30.6	6.5, 85.8
Railway Well#1	30.7	4.9, 64.7
Railway Well#2	32.2	5.1, 67.3
Railway Well#3	25.2	2.1, 27.7
Railway Well#4	22.5	2.2, 29
Railway Well#5	36.3	7.5, 99
Railway Well#6	36.7	7.2, 95
Railway Well#7	34.2	3.2, 42.2
Railway Well #8	28.6	4.4, 58.1
Trill Well#8	25.1	Off Line

2.2 River Intake: Page 5

Between May and October the City pumps water from the Englishman River at a maximum rate of 159 l/s (2100 IGPM) to keep up with summer demands. The water in the Englishman river is partially supplied from the Arrowsmith Dam. The Ministry of Environment, Fisheries and The Arrowsmith Water Service (AWS) developed an operating rule curve in an effort to conserve reservoir storage water for critical fisheries rearing periods. A minimum flow is released into the river based on this curve between June 1st and October 31st. (See **Appendix B**)

2.3 Arrowsmith Dam:

The City of Parksville, The Regional District of Nanaimo, and The Town of Qualicum are partners in the Arrowsmith Water Service (AWS). A concrete gravity dam is located at Arrowsmith Lake approximately 19km south of Parksville. It was commissioned in September of 2000. The dam has a capacity of 9,000,000 m³ and is operated and maintained by City of Parksville staff. Water is released to the Englishman river through 2 pipes, a 900 mm and a 600 mm with flows and lake levels monitored by the City's Supervisory Control and Data Acquisition (SCADA) system.

See **Appendix B** for Arrowsmith Dam Lakes Levels 2013.

2.4 Reservoirs:

Water that has been pumped either from the ground or from the river is stored in 4 reservoirs. Reservoirs numbers 1, 2 and 4 are located in the Springwood Water Compound on Despard Road. These 3 are concrete with 2 being partially below ground and one above. Storage capacities are:

- Reservoir #1 616 m³ (135,500 Imp. gal).
- Reservoir #2 2023 m³ (445,000 Imp. gal)
- Reservoir #4 4559 m³ (1,000,000 Imp. gal).


There are 2 additional reservoirs at the Top Bridge Park area, numbers 3 and 5. Reservoir #5 is a glass fused steel tank, Reservoir #3 is a steel tank although currently not in use. Storage capacities are:

- Reservoir #3 671m³ (148,000 Imp. gal.)
- Reservoir #5 4300 m³ (950,000 Imp. gal).

3.0 Distribution System:


The distribution system consists of 48.79 km of PVC (plastic) pipe, 8.0 km of Ductile Iron pipe and 34.2 km of AC (Asbestos Cement) pipe. Sizes range from 100mm (4") to 400mm (16"). There are 469 fire hydrants and one Pressure Reducing Valve (PRV).

Like all municipalities, the infrastructure is aging and water mains are being replaced through capital improvements and development. The following shows the size, age and material of the mains in the Parksville Water System in 2013. Some of these pipes have been replaced since 2013 but newer data has not yet been updated by the Engineering department.




2013 Watermain Diameter Proportions					
Diameter	No Pipes	Distance (km)	Percentage	Туре	
150 mm or less	532	40.17	43.93%	Distribution Mains (F. 400)	
200 mm	297	19.71	21.55%	Distribution Mains 65.48%	
250 mm	152	12.45	13.61%		
300 mm	131	11.81	12.91%	Supply Mains 34.52%	
350 mm and greater	82	7.31	8.00%		
Total:	1194	=91.45	km		

Page 7



2013 Watermain Age Proportions						
Age	No Pipes	Distance (km)	Percentage			
Under 25 Years (≥1989)	719	45.807	50.1%			
25 - 50 Years (1964 - 1988)	604	43.814	47.9%			
Over 50 Years (≤1963)	69	1.83	2.0%			
Total:	1392	91.45	km			




2013 Watermain Material Proportions						
Material Types	Distance (km)	Percentage				
Asbestos Cement	34.233	37.43%				
Ductile Iron	8.041	8.79%				
PVC	48.794	53.36%				
Steel	0.382	0.42%				
Total:	91.45	km				

3.1 Pressure Zones:

The City is divided into 2 pressure zones. A low pressure and a high pressure. The low pressure is a gravity fed system based on the elevation of Reservoir #4 and Reservoir #5. A top water level of 73.74m above sea level (geodetic) gives a range of 55 psi to 85 psi throughout the system, depending on the geographic location.

The high pressure system initially was developed for higher elevation regions of the city that didn't have sufficient pressures or flows to meet fire fighting flows. This high pressure zone has been expanded to areas furthest from the pump stations that lose pressure and flow due to line losses. In order to maintain a balance between high and low pressures but still keep a safe pressure in the lower areas, a PRV was installed to drop the pressure from 80psi to 60psi.

The high pressure water in this zone is supplied from 4 pumps, a 15hp, 2-40hp and a 100 hp. These pumps are controlled through the SCADA system that automatically watches flows and switches on however many pumps it needs to meet the flow requirements.





4.0 SCADA (Supervisory Control and Data Acquisition):

The water system and sewer pump stations are controlled by a computerized control system called SCADA. This system allows the Operators to monitor reservoir levels, the on/off status and flows of pumps, and monitor chlorine residuals. The operator can change set points and monitor the system remotely. Alarms are automatically called out to City staff that monitor the system 24 hours a day, 7 days a week.



5.0 Water Sampling and Testing

5.1 Bacteriological

As required by the Vancouver Island Health Authority (VIHA), City staff take weekly bacteriological samples to be tested for Total Coliforms and e-Coli Bacteria. There are 16 dedicated sampling sites throughout the city.

See **Appendix D** for 2013 test results (L1 means Less than 1 - Acceptable)

5.2 Full Spectrum Analysis

In addition to weekly sampling throughout the distribution system, the City also sends samples from the source waters once per year, in the Fall, for a full spectrum analysis. As seen in Appendix E, parameters such as metals (iron, manganese) conventional parameters (pH, Turbidity, Hardness) and disinfection byproducts (Trihalomethane) are tested.

The source water is aesthetically acceptable as set by the "Guidelines for Canadian Drinking Water Summary Table". Aesthetic qualities apply to certain substances or characteristics such as high Iron content which will stain fixtures red or Manganese which will stain black.

Hardness in the water comes from calcium carbonate (CaCO3). The river water is considered "Soft" under the guidelines and the Well water is "Moderate". Hardness levels above 500 mg/l are normally considered unacceptable.

All parameters meet the Canadian Drinking Water Guidelines.

See **Appendix E** for the 2013 Full Spectrum Analysis of the Parksville Water System Source Water. Note: The water tested is in it's Raw form before any type of treatment.



6.0 Water Quality Complaints

The Engineering and Operations Department had very few water quality complaints throughout 2013. During periods of high flows or during water main flushing and fire hydrant maintenance there were a few calls related to "brown or dirty" water. A majority of these complaints were on dead end lines. City of Parksville crews would either reflush the mains through a hydrant or flushout at a spot closest to the dead end or advise the homeowner that running an outside tap for a few minutes would clear up the problem.

There were occasional complaints about the taste of chlorine in the water. Chlorine residuals are tested weekly throughout the system and are kept at a safe level. Besides recommending a filter to remove the chlorine within the home, not much can be done about it.

There were a few hardness related complaints mostly contributed to new homeowners from other municipalities who are used to different water composition. There were also a few concerns about calcium build up in washing machines and dishwashers although the water is only considered "Moderately Hard" on the Hardness Scale. This rating drops throughout the summer when the river supply is mixed with the well supply. The river water is considered "Soft".



7.0 Englishman River Water Service Joint Venture Agreement

In June 2011, the partners in the Arrowsmith Water Service (AWS) renewed a revised AWS joint venture agreement. The agreement now addresses governance and funding of the bulk water service without referencing participation in the next phase of capital infrastructure. This change addresses Qualicum Beach's interest in not wishing to cost share in the water intake, treatment plant and distribution infrastructure at this time.

Voting of the AWS management board follows a weighted vote system rather than a unanimous vote system to better reflect a governance model that is similar to a regional district governance structure.

The Englishman River Water Service joint venture agreement parallels and complements the Arrowsmith Water Service joint venture agreement; it has only the City of Parksville and the Regional District of Nanaimo as joint venture participants.

The Englishman River Water Service joint venture agreement describes the infrastructure (intake and treatment plant) that will be cost shared by its two joint venture participants, and contains language that gives the option for the Town of Qualicum Beach to join the agreement in the future. While the Town of Qualicum Beach would not be a signatory to the Englishman River joint venture agreement, under the AWS Agreement the town would have the option to "buy in" to this infrastructure at a future date. Qualicum Beach would have the right to do so due to the rights it possesses as a joint venture partner on the AWS water licence for the Englishman River and as joint owner of the Arrowsmith Lake dam and related infrastructure.

Englishman River Water Service joint venture agreement (percentages of interest).

- City of Parksville 74%
- Regional District of Nanaimo 26%

City of Parksville staff completed a year long water quality monitoring program of the Englishman River. This data was used to determine the best type of treatment process for a water treatment plant. Membrane technology has been chosen. A consultant will be chosen to complete the design of the plant and intake structure.

For more information visit www.arrowsmithwaterservice.ca



8.0 Routine Maintenance Program

8.1 Distribution

- Water mains are flushed using a unidirectional flushing program
- · Air relief valves are cleaned
- Fireline meters are cleaned
- Fire Hydrants are completely disassembled and inspected on a 2 year rotation
- Paint and brush out around hydrants as needed
- All irrigation backflow prevention devices tested and repaired if needed

8.2 Wells

- Daily security check of all wells
- Rehabilitation of 1-2 wells per year
- Pumps and motors replaced as necessary
- Filling chlorine tank on Springwood Well #1 as needed
- Annual water sampling

8.3 River Intake

- Winter maintenance of chlorination system while off line
- Weekly blowing of air lines through intake screens
- Daily checks of pump flows and chlorine levels
- Monthly calibration of turbidity analyzers

8.4 Reservoirs

- Daily security check of tanks and compounds
- Yearly cleaning of Reservoir #1 and 2.
- Clean Reservoir #4 and 5 using divers every 5 years.
- Sustaining valves cleaned monthly

8.5 Pump Stations

- Daily checks of pumps and chlorination system
- Security checks of compounds
- Bi-Annual calibration of chlorine analyzers and turbidimeters

9.0 2013 Improvements:

- Rebuilt 40 HP pump/motor at Springwood pump station.
- Cross Connection tracking program.
- Well rehabilitation of Springwood #3 and Railway #2.
- Completed 3" and 4" meter replacement, started on 2" meter replacement.
- Arrowsmith Dam road maintenance.
- Replaced ultrasonic flow meters at Arrowsmith Dam.
- Replaced antenna at Cokely Mountain.
- New 150mm water service to Community Park Sports Field.
- Reservoir cleaning—All tanks.

10.0 2013 Capital Projects:

- Completed Bay Avenue Realignment (Hwy 19): water.
- Completed Dogwood: Bay to SRW: water, sewer, storm.
- Started Temple Street water/sewer/storm plans for upgrades.
- Watermain upgrades on the Island Highway—Moilliet to Temple.
- ASR well—full scale cycle test.

11.0 2014 Capital Projects and Improvements:

- Springwood Well#2 abandonment.
- Continuing the water meter replacement program.
- Continuing to replace aging water mains for better distribution (Temple Street scheduled).
- Continue developing the Cross Connection Control Program.
- Water Treatment Plant pre-design.
- Installation of a new sports field meter at Springwood Park.
- Rebuild 100 HP & 40 HP pumps at Springwood pump station.

12.0 Cross Connection Control Program

In May 2006 the City of Parksville developed a draft cross connection control program as is currently working on the implementation of it.

The cross connection program will be implemented in a manner that will address high and severe hazard water use processes first. These include Industrial, Commercial and Institutional (ICI) users. Each ICI user will be assessed as to the potential risk to the water system. An approved backflow device will have to be installed.

All City owner facilities were assessed and appropriate backflow installed. A tracking program called FAST was installed to track devices around the City and produce letters reminding businesses of when testing is due.

City staff remain watchful of potential cross connections in the fields and report problems back to Cross Connection Control Coordinator.




Double Check Valve Assembly


13.0 Emergency Response Plan

The City of Parksville has an Emergency Response Plan pertaining to the water system available for public viewing at the Engineering and Operations Department. This document outlines the strategies to deal with events such as contamination of water supply, pump failures and turbidity events. This plan continues to be updated.

Water Source Locations Map Overview Map Railway Wells



Map of Pressure Zone Boundaries



Water Sample Range Report for PARKSVILLE, WWS

Page 1 of 7

Water Sample Range Report

Island Health

Facility Name: PARKSVILLE, WWS

Facility Type: DWT

Date Range:

Jan 1 2013 to Dec 31 2013

Date Created: Feb 21 2014

Parksville BC, Parksville MHP/Utility Building, Parksville, Dist site. Monthly 1/2/2013 L1 L1	Sampling Site	Date Collected	Total Coliform	E. Coli	Fecal Coliform
Parksville BC, Despard & Moilliet, Dist. site, Monthly 1/29/2013	401 S. Moiliet Street				
Despard & Moilliet, Dist. site, Monthly 1/29/2013 L1 L1 L1					
1/29/2013 L1 L1 3/27/2013 L1 L1 3/27/2013 L1 L1 4/30/2013 L1 L1 5/14/2013 L1 L1 6/11/2013 L1 L1 7/31/2013 L1 L1 8/20/2013 L1 L1 9/3/2013 L1 L1 10/29/2013 L1 L1 11/19/2013 L1 L1 12/10/2013 L1 L1 12/5/2013 L1 L1 3/5/2013 L1 L1 4/2/2013 L1 L1 5/8/2013 L1 L1 1/7/2/2013 L1 1/7/2/2013 L1 1/7	Despard & Moilliet,				
2/19/2013	Dist. site, Monthly				
3/27/2013 L1 L1 4/30/2013 L1 L1 5/14/2013 L1 L1 6/11/2013 L1 L1 6/11/2013 L1 L1 8/20/2013 L1 L1 11/19/2013 L1 L1 11/19/2013 L1 L1 11/19/2013 L1 L1 11/19/2013 L1 L1 12/10/2013 L1 L1 12/5/2013 L1 L1 3/5/2013 L1 L1 4/2/2013 L1 L1 5/8/2013 L1 L1 11/10/2013 L1 L1 11/10/1/2013 L1 L1 11/5/2013 L1 11/5/		1/29/2013	L1	L1	
### ### ##############################		2/19/2013	L1	L1	
5/14/2013		3/27/2013	L1	L1	
6/11/2013 L1 L1 7/31/2013 L1 L1 8/20/2013 L1 L1 10/29/2013 L1 L1 11/19/2013 L1 L1 2/19/2013 L1 L1 2/5/2013 L1 L1 3/5/2013 L1 L1 4/2/2013 L1 L1 5/8/2013 L1 L1 6/5/2013 L1 L1 6/5/2013 L1 L1 1/19/2013 L1 1/		4/30/2013	L1	L1	
7/31/2013 L1 L1 8/20/2013 L1 L1 9/3/2013 L1 L1 10/29/2013 L1 L1 11/19/2013 L1 L1 12/10/2013 L1 L1 13/25/2013 L1 L1 2/5/2013 L1 L1 3/55/2013 L1 L1 4/2/2013 L1 L1 5/8/2013 L1 L1 6/5/2013 L1 L1 6/5/2013 L1 L1 6/5/2013 L1 L1 1/10/2013 L				L1	
8/20/2013 L1 L1 9/3/2013 L1 L1 10/29/2013 L1 L1 11/19/2013 L1 L1 12/10/2013 L1 L1 12/10/2013 L1 L1 12/10/2013 L1 L1 15/10/2013 L1 L1 15/10/2013 L1 L1 16/10/2018 L1 L1 17otal Positive: 0 0 0 1247 Arbutus Road. Parksville BC. Parksville BC. Parksville BC. Parksville Dist. site. Monthly 1/2/2013 L1 L1 2/5/2013 L1 L1 5/8/2013 L1 L1 5/8/2013 L1 L1 6/5/2013 L1 L1 17/2/2013 L1 L1 17/2/2013 L1 L1 17/2/2013 L1 L1 18/6/2013 L1 L1 19/3/2013 L1 L1 11/5/2013			77.5		
9/3/2013			3753730	L1	
10/29/2013				L1	
11/19/2013 L1 L1 12/10/2013 L1 L1 Total Positive: 0 0 0 0 1247 Arbutus Road. Parksville BC. Parksville BC. Parksville Dist site. Monthly 1/2/2013 L1 L1 3/5/2013 L1 L1 4/2/2013 L1 L1 5/8/2013 L1 L1 5/8/2013 L1 L1 5/8/2013 L1 L1 5/8/2013 L1 L1 6/5/2013 L1 L1 1/7/2/2013 L1 L1			177/16	L1	
12/10/2013 L1 L1 Total Positive: 0 0 0 0 1247 Arbutus Road, Parksville BC, Parksville BC, Parksville, Dist site. Monthly 1/2/2013 L1 L1 2/5/2013 L1 L1 3/5/2013 L1 L1 4/2/2013 L1 L1 5/8/2013 L1 L1 5/8/2013 L1 L1 5/8/2013 L1 L1 5/8/2013 L1 L1 17/2/2013 L1 L1 11/5/2013 L1 L1			-		
Total Positive: 0 0 0 0 1247 Arbutus Road, Parksville BC, Parksville BC, Parksville Dist. site. Monthly 1/2/2013		10000111 11 교육 (기교 1917)			
1247 Arbutus Road. Parksville BC. Parksville BC. Parksville MHP/Utility Building. Parksville, Dist. site. Monthly 1/2/2013					
Parksville BC, Parksville MHP/Utility Building, Parksville, Dist site. Monthly 1/2/2013 L1 L1		Total Positive:	0	0	0
Parksville MHP/Utility Building, Parksville, Dist. site. Monthly 1/2/2013	1247 Arbutus Road,				
MHP/Utility Building, Parksville, Dist. site. Monthly 1/2/2013					
Parksville, Dist. site. Monthly					
Monthly					
1/2/2013 L1 L1 2/5/2013 L1 L1 3/5/2013 L1 L1 4/2/2013 L1 L1 5/8/2013 L1 L1 6/5/2013 L1 L1 7/2/2013 L1 L1 8/6/2013 L1 L1 8/6/2013 L1 L1 9/3/2013 L1 L1 10/1/2013 L1 L1 11/5/2013 L1 L1 12/4/2013 L1 L1 Total Positive: 0 0 0 Harbour Homes, Parksville BC, Top of Corfield, Parksville Dist. site, Monthly 1/2/2013 L1 L1 2/5/2013 L1 L					
2/5/2013 L1 L1 3/5/2013 L1 L1 4/2/2013 L1 L1 5/8/2013 L1 L1 6/5/2013 L1 L1 7/2/2013 L1 L1 8/6/2013 L1 L1 8/6/2013 L1 L1 9/3/2013 L1 L1 10/1/2013 L1 L1 11/5/2013 L1 L1 11/5/2013 L1 L1 11/5/2013 L1 L1 12/4/2013 L1 L1 Total Positive: 0 0 0 Harbour Homes. Parksville BC, Top of Corfield. Parksville , Dist. site. Monthly 1/2/2013 L1 L1 2/5/2013 L1 L1 2/5/2013 L1 L1 11 12/2013 L1 L1 12/2013 L1 L1 11 12/2013 L1 L1 12/2013 L1 L1 11 11 11 11 11 11 11 11 11 11 11 11 1	monuny	1/2/2013	14	1.1	
3/5/2013 L1 L1 4/2/2013 L1 L1 5/8/2013 L1 L1 6/5/2013 L1 L1 7/2/2013 L1 L1 8/6/2013 L1 L1 8/6/2013 L1 L1 9/3/2013 L1 L1 10/1/2013 L1 L1 11/5/2013 L1 L1 11/5/2013 L1 L1 11/5/2013 L1 L1 12/4/2013 L1 L1 Total Positive: 0 0 0 Harbour Homes. Parksville BC, Top of Corfield. Parksville Dist. site. Monthly 1/2/2013 L1 L1 2/5/2013 L1 L1 2/5/2013 L1 L1 11 12/2013 L1 L1 12/2013 L1 L1 13/2/2013 L1 L1 14 15/5/2013 L1 L1 15/5/2013 L1 L1 16 17/2/2013 L1 L1 17/2/2013 L1 L1 17/2/2013 L1 L1 18 18 18 18 18 18 18 18 18 18 18 18 18					
### Add ### Ad					
5/8/2013 L1 L1 6/5/2013 L1 L1 7/2/2013 L1 L1 8/6/2013 L1 L1 9/3/2013 L1 L1 10/1/2013 L1 L1 11/5/2013 L1 L1 11/5/2013 L1 L1 12/4/2013 L1 L1 Total Positive: 0 0 0 Harbour Homes. Parksville BC, Top of Corfield. Parksville Dist. site. Monthly 1/2/2013 L1 L1 2/5/2013 L1 L			77.7		
6/5/2013 L1 L1 7/2/2013 L1 L1 8/6/2013 L1 L1 9/3/2013 L1 L1 10/1/2013 L1 L1 11/5/2013 L1 L1 11/5/2013 L1 L1 12/4/2013 L1 L1 Total Positive: 0 0 0 Harbour Homes. Parksville BC, Top of Corfield. Parksville, Dist. site. Monthly 1/2/2013 L1 L1					
7/2/2013 L1 L1 8/6/2013 L1 L1 9/3/2013 L1 L1 10/1/2013 L1 L1 11/5/2013 L1 L1 11/5/2013 L1 L1 12/4/2013 L1 L1 Total Positive: 0 0 0 Harbour Homes, Parksville BC, Top of Corfield, Parksville , Dist. site. Monthly 1/2/2013 L1 L1 2/5/2013 L1 L					
8/6/2013 L1 L1 9/3/2013 L1 L1 10/1/2013 L1 L1 11/5/2013 L1 L1 12/4/2013 L1 L1 Total Positive: 0 0 0 Harbour Homes. Parksville BC, Top of Corfield. Parksville , Dist. site. Monthly 1/2/2013 L1 L1 2/5/2013 L1 L					
9/3/2013 L1 L1 10/1/2013 L1 L1 11/5/2013 L1 L1 12/4/2013 L1 L1 Total Positive: 0 0 0 Harbour Homes. Parksville BC, Top of Corfield. Parksville , Dist. site. Monthly 1/2/2013 L1 L1 2/5/2013 L1 L					
10/1/2013 L1 L1 11/5/2013 L1 L1 12/4/2013 L1 L1 Total Positive: 0 0 0 Harbour Homes. Parksville BC, Top of Corfield. Parksville , Dist. site. Monthly 1/2/2013 L1 L1 2/5/2013 L1 L					
11/5/2013 L1 L1 12/4/2013 L1 L1 Total Positive: 0 0 0 Harbour Homes. Parksville BC, Top of Corfield. Parksville , Dist. site. Monthly 1/2/2013 L1 L1 2/5/2013 L1 L1			77.65		
12/4/2013 L1 L1 Total Positive: 0 0 0 Harbour Homes. Parksville BC, Top of Corfield. Parksville , Dist. site. Monthly 1/2/2013 L1 L1 2/5/2013 L1 L1					
Total Positive: 0 0 0 Harbour Homes, Parksville BC, Top of Corfield, Parksville , Dist. site, Monthly 1/2/2013 L1 L1 2/5/2013 L1 L1					
Harbour Homes. Parksville BC, Top of Corfield. Parksville , Dist. site. Monthly 1/2/2013 L1 L1 2/5/2013 L1 L1					0
Parksville BC, Top of Corfield, Parksville , Dist. site, Monthly 1/2/2013					
of Corfield, Parksville , Dist. site. Monthly 1/2/2013	Harbour Homes,				
Parksville , Dist. site. Monthly	of Corfield				
Monthly 1/2/2013 L1 L1 2/5/2013 L1 L1	Parksville Diet eite				
1/2/2013 L1 L1 2/5/2013 L1 L1	Monthly				
2/5/2013 L1 L1	monent	1/2/2013	11	1.1	
		The state of the s		1077.57	
		3/5/2013	Ĺ1	L1	

Water Sample Range Re	port fd/9/28%SVILLE, WWS 5/18/2013 6/18/2013 7/9/2013 8/13/2013 9/17/2013 10/22/2013 11/19/2013 12/10/2013 Total Positive:	L1 L1 L1 L1 L1 L1 L1 L1 L1	L1 L1 L1 L1 L1 L1 L1 L1 L1	Page 2 of 7
1390 Herring Gull Way, Parksville BC, Works Yard, Parksville, Dist, site, Monthly	1/15/2013 2/13/2013 3/12/2013 4/9/2013 5/14/2013 6/11/2013 7/9/2013	L1 L1 L1 L1 L1 L1	11 11 11 11 11 11	
613 Chinook Avenue, Parksville	8/20/2013 9/10/2013 10/8/2013 11/13/2013 12/10/2013 Total Positive:	L1 L1 L1 L1 <u>L1</u>	L1 L1 L1 L1 <u>L1</u>	0
BC, 613 Chinook Avenue, Parksville Dist. site, Monthly	1/2/2013 2/5/2013 3/12/2013 4/9/2013 5/8/2013 6/5/2013 7/31/2013 9/17/2013 10/1/2013 11/13/2013 12/17/2013 Total Positive:	L1 L1 L1 L1 L1 L1 L1 L1 L1 L1 L1 L1	L1 L1 L1 L1 L1 L1 L1 L1 L1 L1 L1	0
193 East Island Highway, Parksville BC, Community Park, Parksville BC, Dist. site, Monthly	1/29/2013 2/5/2013 3/5/2013 4/2/2013	L1 L1 L1 L1	L1 L1 L1 L1	

APPENDIX D

2013 Bacteriological Results

Water Sample Range Re	6/18/2013 7/2/2013 8/13/2013 9/17/2013 10/8/2013 11/5/2013 12/4/2013 Total Positive:	L1 L1 L1 L1 L1 L1 L1	L1 L1 L1 L1 L1 L1 L1 L1	Page 3 of 7
249 West Hirst Avenue, Parksville BC, Health Unit, Audit TAP in kitchen, parksville BC, Dist. site, No Regular Sampling	1/9/2013 Total Positive:	<u>L1</u>	<u>L1</u> 0	0
271 Chestnut Street, Parksville BC, 271 Chestnut Street, Parksville, Dist, site,				
<u>Monthly</u>	1/22/2013 2/27/2013 3/19/2013 5/22/2013 6/18/2013 7/17/2013 8/13/2013 9/17/2013 10/8/2013 11/26/2013 Total Positive:	11 11 11 11 11 11 11 11 11	L1 L1 L1 L1 L1 L1 L1 L1 L1	0
Englishman River Intake, River Pump Station, Dist. site, Monthly	Total Fositive.	·	·	
	1/8/2013 2/19/2013 3/19/2013 5/22/2013 6/25/2013 7/17/2013 8/27/2013 9/3/2013 9/25/2013 10/29/2013 11/26/2013 12/10/2013 Total Positive:	L1 L1 L1 L1 L1 L1 95.9 L1 L1 L1 L1	L1 L1 L1 L1 L1 L1 L1 L1 L1 L1	0

Daffodil at Camas,

Waleaßaville Radge R Daffodil at Carnas, Parksville, Dist. site, Monthly	Report for PARKSVILLE, V	vws		Page 4 of 7
	1/8/2013	L1	L1	
	2/27/2013	L1	L1	
	3/27/2013 4/30/2013	L1 L1	L1 L1	
	5/28/2013	L1	L1	
	6/25/2013	L1	L1	
	7/23/2013	L1	L1	
	8/20/2013	L1	L1	
	9/25/2013	L1	L1	
	10/29/2013	L1	L1	
	11/26/2013	L1	L1	
	12/17/2013	L1	<u>L1</u>	
	Total Positive:	0	0	0
330 Park View, Parksville BC, 330 Park View, Parksville, Dist. site, Monthly				
monuny	1/22/2013	L1	L1	
	2/13/2013	L1	L1	
	3/12/2013	L1	L1	
	4/16/2013	L1	L1	
	5/8/2013	L1	L1	
	6/5/2013	L1	L1	
	7/23/2013	L1	L1	
	8/6/2013	L1	L1	
	9/10/2013	L1	L1	
	10/16/2013 11/19/2013	L1 L1	L1 L1	
	12/4/2013	11	<u>L1</u>	
	Total Positive:	0	0	0
851 Temple, 851 TEMPLE (beside), Dist. site, Monthly				
	1/8/2013	L1	L1	
	2/27/2013	L1	L1	
	3/19/2013	L1	L1	
	4/16/2013	L1	L1	
	5/22/2013	L1	L1	
	6/11/2013	L1	L1	
	7/9/2013	L1	L1	
	8/20/2013	L1	L1	
	9/3/2013 9/9/2013	1 L1	L1 L1	
	10/16/2013	L1	L1	
	11/5/2013	L1	Ľ1	
	12/4/2013	<u>L1</u>	<u>L1</u>	
	Total Positive:	1	0	0

378 Kingsley Street. Wheeler, Top of Kingsley, Dist. site.

Water Strongth Range Report for PA 1/15/2 2/19/2	2013	L1 L1	L1 L1	Page 5 of 7
3/27/2 5/8/2	013	L1 L1	L1 L1	
6/5/2 7/2/2		L1 L1	L1 L1	
8/6/2	013	L1	L1	
9/10/2 10/1/2		L1 L1	L1 L1	
11/13/	2013	L1	L1	
12/17/ Total Po		<u>L1</u> 0	<u>L1</u> 0	0
Island Highway, by Temple, Island Highway, by Temple, Dist, site, Monthly				
1/22/2		L1 L1	L1	
3/27/2	2013	L1	L1	
4/30/2 5/28/2		L1 L1	L1 L1	
6/25/2	2013	L1	L1	
7/31/2 8/27/2		L1 L1	L1 L1	
9/25/2		Li	L1	
10/22/ 11/26/		L1 L1	L1 L1	
12/17/ Total Po		<u>L1</u> 0	<u>L1</u>	0
Total C	oluvo.	v	•	•
136 Memorial, 136 Memorial, Dist. site, Monthly			224	
1/29/2 2/27/2		L1 L1	L1 L1	
3/19/2	2013	L1	L1	
4/30/2 5/28/2		L1 L1	L1 L1	
6/18/2 7/23/2		L1 L1	L1 L1	
8/27/2	2013	L1	L1	
9/25/2 10/1/2	2013	L1 L1	L1 L1	
11/13/	2013	L1	L1	
12/17/ Total Po		<u>L1</u>	<u>L1</u>	0
7 3 441 7 9				ř
450 Wisteria, across from 450 Wisteria, Dist. site, Monthly				
1/15/2 2/13/2		L1 L1	L1 L1	
3/5/2	013	L1	L1	
4/2/20 5/14/2		L1 L1	L1 L1	
6/25/2		148	ī.i	

Water Sample Range Re	8/6/2013 9/10/2013 10/8/2013 11/19/2013 11/19/2013 12/10/2013 Total Positive:	11 11 11 11 11 11	L1 L1 L1 L1 L1 L1	Page 6 of 7
770 Soriel, 770 Soriel , Dist. site, Monthly				
	1/22/2013	L1	L1	
	2/13/2013	L1	L1	
	3/12/2013	L1	L1	
	4/16/2013	L1	L1	
	5/22/2013	L1	L1	
	6/11/2013	L1	L1	
	7/17/2013	L1	L1	
	8/27/2013	L1	L1	
	9/3/2013	L1	L1	
	10/16/2013	L1	L1	
	11/5/2013	L1	L1	
	12/4/2013	L1	<u>L1</u>	
	Total Positive:	0	0	0
491 Island Highway, East, City of Parksville, 491 Island Hwy, Audit, Dist. site, No Regular Sampling				
	1/8/2013	<u>L1</u>	<u>L1</u>	
-	Total Positive:	0	0	0

Result Values:

E - estimated

L - less than

G - greater than

Interpreting Sample Reports
In VIHA, the results of drinking water sampling are reported using the following coding system: L1 Less than 1 (no detectable bacteria) - Meaning: No bacteria present OG Overgrown - Meaning: Too many background bacteria to give an accurate count **EST** Estimated Count

and

A Sample not tested; Too long in transit

C Sample leaked/broken in transit

D Sample not tested; No collection date given
T Sample submitted unsatisfactory. Exceeded 30 hours holding time, please resample. NS No sample received with requisition

Water Sample Range Report for PARKSVILLE, WWS

Page 7 of 7

Samples that contain total coliform:	3	1.55% of total
Samples that contain e. coli:	0	0.00% of total
Samples that contain fecal coliform:	0	0.00% of total
Number of positive samples in last 30	0/16	
days:		
Total number of samples:	193	

Comments:

Environmental Health Officer May 13 2014

FOR FURTHER INFORMATION PLEASE CALL: Wrathall, Bill (250) 947-8222 Parksville

Operator

City of Parksville 1116 Herring Gull Way Parksville, BC V9P 2H3

(250) 248-5412



Success Through Sciences

Your P.O. #: S13-5065 Your C.O.C. #: G071735

Attention: Scott Churko
City of Parksville
Engineering and Operations Dpt
PO Box 1390
Parksville, BC
Canada V9P 2H3

Report Date: 2013/11/29

CERTIFICATE OF ANALYSIS

MAXXAM JOB #: B3A9396 Received: 2013/11/26, 08:45

Sample Matrix: Water # Samples Received: 4

		Date	Date		
Analyses	Quantity	Extracted	Analyzed	Laboratory Method	Analytical Method
Alkalinity - Water	4	2013/11/26	2013/11/26	BBY6SOP-00026	SM2320B
Chloride by Automated Colourimetry	3	N/A	2013/11/27	BBY6SOP-00011	SM-4500-CI-
Chloride by Automated Colourimetry	1	N/A	2013/11/28	BBY6SOP-00011	SM-4500-CI-
Coliform by membrane filtration	4	N/A	2013/11/26	BBY4SOP-00001	Based on SM-9222
E.coli by membrane filtration in Water	4	N/A	2013/11/26	BBY4SOP-00001	Based on SM-9222
Conductance - water	4	N/A	2013/11/26	BBY6SOP-00026	SM-2510B
Fluoride	4	N/A	2013/11/27	BBY6SOP-00012	SM - 4500 F C
Fecal Coliform by membrane filtration	4	N/A	2013/11/26	BRN SOP 00363 R2.0	Based on SM-9222
Hardness Total (calculated as CaCO3)	1	N/A	2013/11/28	BBY7SOP-00002	EPA 6020A
Hardness Total (calculated as CaCO3)	3	N/A	2013/11/29	BBY7SOP-00002	EPA 6020A
Hardness (calculated as CaCO3)	4	N/A	2013/11/27	BBY7SOP-00002	EPA 6020A
Na, K, Ca, Mg, S by CRC ICPMS (diss.)	4	N/A	2013/11/27	BBY7SOP-00002	EPA 6020A
Elements by CRC ICPMS (dissolved)	4	N/A	2013/11/27	BBY7SOP-00002	EPA 6020A
Na, K, Ca, Mg, S by CRC ICPMS (total)	1	2013/11/26	2013/11/28	BBY7SOP-00002	EPA 6020A
Na, K, Ca, Mg, S by CRC ICPMS (total)	3	2013/11/26	2013/11/29	BBY7SOP-00002	EPA 6020A
Elements by CRC ICPMS (total)	1	2013/11/27	2013/11/27	BBY7SOP-00002	EPA 6020A
Elements by CRC ICPMS (total)	3	2013/11/28	2013/11/28	BBY7SOP-00002	EPA 6020A
Ammonia-N (Unpreserved)	4	N/A	2013/11/26	BBY6SOP-00009	SM-4500NH3G
Nitrate + Nitrite (N)	4	N/A	2013/11/26	BBY6SOP-00010	SM 4500NO3-I
Nitrite (N) by CFA	4	N/A	2013/11/26	BBY6SOP-00010	EPA 353.2
Nitrogen - Nitrate (as N)	4	N/A	2013/11/26	BBY6SOP-00010	SM 4500NO3-I
Filter and HNO3 Preserve for Metals	4	N/A	2013/11/26	BBY6WI-00001	EPA 200.2
pH Water (1)	4	N/A	2013/11/26	BBY6SOP-00026	SM-4500H+B
Silica (Reactive)	4	N/A	2013/11/26	BBY6SOP-00014	SM - 4500SiO2
Sulphate by Automated Colourimetry	4	N/A	2013/11/27	BBY6SOP-00017	SM4500-SO42- E
Total Dissolved Solids (Filt. Residue)	4	2013/11/26	2013/11/26	BBY6SOP-00033	SM 2540C
Tannin & Lignin (Total)	4	N/A		BRN SOP-00221 R1.0	SM-5550 B
Total Suspended Solids	4	N/A		BBY6SOP-00034	SM - 2540 D

^{*} Results relate only to the items tested.

⁽¹⁾ The BC-MOE and APHA Standard Method require pH to be analysed within 15 minutes of sampling and therefore field analysis is required for compliance. All Laboratory pH analyses in this report are reported past the BC-MOE/APHA Standard Method holding time.



Success Through Sciences

Maxxam Job #: B3A9396

Report Date: 2013/11/29

City of Parksville

Your P.O. #: S13-5065

-2-

Encryption Key



Manoram

29 Nov 2013 16:16:59 -08:00

Please direct all questions regarding this Certificate of Analysis to your Project Manager.

Samantha Fregien, Project Manager Email: SFregien@maxxam.ca Phone# (604) 734 7276

This report has been generated and distributed using a secure automated process.

Maxxam has procedures in place to guard against improper use of the electronic signature and have the required "signatories", as per section 5.10.2 of ISO/IEC 17025:2005(E), signing the reports. For Service Group specific validation please refer to the Validation Signature Page.

Bicarbonate (HCO3)
Carbonate (CO3)
Hydroxide (OH)

mg/L mg/L mg/L

0.062 101 40.50 40.50 40.50

7298148 7298148

0.058 40.50 40.50 40.50

7298148 7298148

94.9 <0.50 0.050

0.010 7298603 0.50 7298148 0.50 7298148

0.058 108 132 40.50

7299603

7298148 7298148 7298148

7298148 7298148 7298148

116 <0.50

0.50 0.50

7298148 7298148 7298148

Alkalinity (Total as CaCO3) Alkalinity (PP as CaCO3)

Misc. Inorganics

Dissolved Sulphate (SO4)
Dissolved Chloride (CI)
MISCELLANEOUS

mg/L

528 15

7299980 7299978

6.02 20

7299980 7301558

821 23

5.27 52

0.50

annins and Lignins monia (N)

mg/L

<u>0.10</u>

Calculated Parameters
Filter and HNO3 Preservation

mg/L

LAB 1.37

7297401 7297137

LAB 0.883

7297401 7297137

LAB 0.950

LAB 0.861

N/A 7297401 0.020 7297137

Nitrite (N)



Maxxam Job #: B3A9396 Report Date: 2013/11/29

Maxxam ID Sampling Date

STINO

SPRINGWOOD WELL #1 013/11/25 13:20

QC Batch

SPRINGWOOD WELL #3 2013/11/25 13:30

QC Batch

IE3472 IE3473
2013/11/25 2013/11/25
13:55 14:10
RAILWAY RAILWAY
WELL#1 WELL#3

R

QC Batch

<0.0050 24.1

7298096 7295669

0.0101 22.6

7298096 <0.0050 7295669 21.7

<0.0050

0.0050 7298096 0.50 7295669

RESULTS OF CHEMICAL ANALYSES OF WATER

Your P.O. #: S13-5065

City of Parksville

N/A = Not Applicable RDL = Reportable Detection Limit

Physical Properties
Total Suspended Solids
Total Dissolved Solids

Nitrate plus Nitrite (N) Physical Properties

mg/L

<0.0050 1.37

7297556 7297472 7298123

0.0135 0.883 <u>@</u>

7297556 7297472 7298123

0.0066

<0.0050

296 7.87

365 7.85

<4.0 170

100

<0.10 <0.10

0.10 7298123

pH Units

258 7.66

7298150 7298149

Maxxam Job #: B3A9396 Report Date: 2013/11/29

MICROBIOLOGY (WATER)

STINU

SPRINGWOOD SPRINGWOOD WELL #1 WELL #3

RDL

IE3472 IE3473
2013/11/25 2013/11/25
13:55 14:10
RAILWAY RAILWAY
WELL #1 WELL #3

RDL

QC Batch

1E3470 1E3471 2013/11/25 13:202013/11/25 13:30

Your P.O. #: S13-5065

City of Parksville

Page 4 of 14

RDL = Reportable Detection Limit

Dissolved Nickel (Ni)
Dissolved Selenium (Se)
Dissolved Silicon (Si)

ssolved Strontium (Sr) ssolved Thallium (TI) ssolved Silver (Ag)

1.1 -0.50 0.98 -6.0 -6.0 -6.0 -6.0 -6.0 -6.0 -6.0 -1.1 0.11 1.1 1.1 1.1 1.1 1.1 0.11

41.0 40.50 0.80 45.0 40.0 40.0 41.0 41.0 41.0 41.0 41.0 41.0 41.0 40.0

1.0 0.10 100 0.020 1.0 0.050 5.0 5.0 5.0 5.0 0.150 0.050 0.050 0.050

7299192 7299192 7299192 7299192 7299192 7299192 7299192 7299192 7299192 7299192 7299192 7299192 7299192 7299193 7297135

issolved Lead (Pb)

ssolved Copper (Cu) ssolved Iron (Fe)

19/L

40.20 40.20 45.0 45.0 45.0 45.0 45.0 45.0 45.0

0.50 0.20 0.20 0.20 0.050

1.0

ssolved Lithium (Li)

ssolved Manganese (Mn)

19/1

solved Molybdenum (Mo) olved Mercury (Hg) Misc. Inorganics
Dissolved Hardness (CaCO3)
Dissolved Metals by ICPMS
Dissolved Aluminum (Al)
Dissolved Arimony (Sb)
Dissolved Arsenic (As)
Dissolved Barium (Ba)

issolved Bismuth (Bi) issolved Boron (B)

\$1.0 \$50

\$1.0 \$0.010

7299192 7299192 7299192 7299192 7299192 7299192 7299192 7299192 7299192 7299192 7299192 7299192 7299192 7299192 7299192 7299192 7299192 7299192 7299192

issolved Cadmium (Cd)

Maxxam Job #. B3A9396 Report Date: 2013/11/29

Sampling Date

STINU

SPRINGWOOD WELL #1

SPRINGWOOD RAILWAY WELL #1 RAILWAY WELL #3
WELL #3

116

120

131

152

0.50

7297122

RDL

QC Batch

CSR DISSOLVED METALS IN WATER (WATER)

2013/11/25 13:20:2013/11/25 13:30 2013/11/25 13:55 2013/11/25 14:10

Your P.O. #: S13-5085

City of Parksville

RDL = Reportable Detection Limit

issolved Zirconium (Zr) issolved Vanadium (V) issolved Zinc (Zn)

issolved Uranium (U) ssolved Titanium (Ti)



Maxxam Job #: B3A9396 Report Date: 2013/11/29

CSR DISSOLVED METALS IN WATER (WATER)

 SPRINGWOOD
 SPRINGWOOD
 RAILWAY WELL #1
 RAILWAY WELL #3

 WELL #1
 WELL #3
 7.36
 7.96

RP

QC Batch

Your P.O. #: S13-5065

City of Parksville

RDL = Reportable Detection Limit

otal Lithium (Li) otal Mercury (Hg) otal Manganese (Mn)

1/gu

ug/L

18 M

76.3 -0.50 -0.034 -0.034 -0.034 -0.034 -0.034 -0.034 -0.034 -0.031 -

Total Aluminum (Al)
Total Antimony (Sb)
Total Arsenic (As)
Total Barium (Ba)
Total Bervillium (Be)
Total Bismuth (Bi)
Total Boron (B)
Total Cadmium (Cd)
Total Chromium (Cr)
Total Cobalt (Co)
Total Copper (Cu)
Total Copper (Cu)

7301221 7301221 7301221 7301221 7301221 7301221 7301221 7301221 7301221 7301221 7301221



Report Date: 2013/11/29

Maxxam ID Sampling Date

E3470 2013/11/25 13:20

IE3471 2013/11/25 13:30

1834/2 2013/11/25 13:55

1E3473 2013/11/25 14:10 RAILWAY WELL #3

Calculated Parameters
Total Hardness (CaCO3)
Total Metals by ICPMS

mg/L

126

7296879

137

7296879

141

163

0.50

UNITS SPRINGWOOD WELL #1

QC Batch

SPRINGWOOD WELL #3

QC Batch RAILWAY WELL #1

RDL

QC Batch

Maxxam Job # B3A9396

CSR TOTAL METALS IN WATER (WATER)

Your P.O. #: S13-5065

City of Parksville

RDL = Reportable Detection Limit

Total Molybdenum (Mo)
Total Nickel (Ni)
Total Selenium (Se)
Total Silion (Si)
Total Silion (Si)
Total Silion (Sr)
Total Strontium (Sr)
Total Thallium (TI)
Total Thallium (TI)
Total Tranium (U)
Total Uranium (V)
Total Zinc (Zn)
Total Zinc (Zn)
Total Zinc (Zn)
Total Calcium (Ca)
Total Magnesium (Mg)
Total Magnesium (Mg)

40.50 -1.44 -1.44 -1.00 -1

7301221 7301231 7301231

40.50 40.00 40

7301221 7301221

1.0 0.050 1.0 1.0 1.0 0.10 0.020 0.020 0.050 5.0 5.0 5.0 5.0 0.050 0.050

Maxxam Job #. B3A9396 Report Date: 2013/11/29

CSR TOTAL METALS IN WATER (WATER) ALS IN WATELY, IE3471 2013/11/25 13:30 2013/11/25 207 2013

SPRINGWOOD QC Batch WELL #1 7207136

IE3473 2013/11/25 14:10 RAILWAY WELL #3 8.52 <3.0

QC Batch

Your P.O. #: S13-5065

City of Parksville

Page 8 of 14

RDL = Reportable Detection Limit

/a XXam

Maxxam Job #: B3A8398 Report Date: 2013/11/29

General Comments

Package 1 2.0°C

Each temperature is the average of up to three cooler temperatures taken at receipt

City of Parksville

Your P.O. #: S13-5065

Success Through Scien

Total Arsenic (As)
Total Barlum (Ba)
Total Beryllum (Be)

Total Antimony (Sb)

<0.50 <0.10

> ug/L uq/L

Total Bismuth (BI)

2013/1/26 2013/1/26 2013/1/26 2013/1/26 2013/1/26 2013/1/26 2013/1/26 2013/1/26 2013/1/26 2013/1/26 2013/1/26 2013/1/26 2013/1/26 2013/1/26 2013/1/26 2013/1/26 2013/1/26 2013/1/27

Tarnins and Lignins
Alkalinity (Total as CaCO3)
Alkalinity (PP as CaCO3)
Blicarbonate (HCO3)
Carbonate (CO3)
Chydroxide (OH)

Total Suspended Solids
Total Dissolved Solids
Nitrate plus Nitrite (N)

2 6 8 6 8 8

80 - 120 80 - 120 80 - 120 80 - 120 80 - 120 80 - 120

80 - 120 80 - 120 80 - 120 80 - 120 80 - 120 80 - 120

80 - 120

NO 6 6 6 6 0 0 0 1 1 0 0 0

Ammonia (N)

Total Cadmium (Cd)
Total Chromium (Cr)
Total Cobalt (Co)
Total Cobalt (Co)
Total Cobalt (Co)
Total Lead (Pb)
Total Lead (Pb)
Total Lithium (Ll)
Total Manganese (Mn)

Total Mercury (Hg)
Total Molybdenum (Mo) Total Nickel (NI)

80 - 120 80 - 120

80 - 120 80 - 120

41.0 40.10 40.10 40.50 40.50 40.50 40.20 40.20

<0.050

20

<0.10

uq/L ug/L UQ/L



QUALITY ASSURANCE REPORT

Matrix Spike

Your P.O. #: S13-5085

Value (%)

RPD QC Limits

City of Parksville

Page 10 of 14

Total Titanium (Ti)
Total Uranium (U)

4000

101 101

Total Thaillum (TI) Total Strontlum (Sr) Total Selenium (Se)

7299192 7299192

Dissolved Lead (Pb)

Dissolved Lithium (LI) Dissolved Iron (Fe) Dissolved Copper (Cu) Dissolved Cobalt (Co) Dissolved Chromium (Cr)

2013/11/27 2013/11/27 2013/11/27 2013/11/27 2013/11/27

80 - 120

<0.050

å

80 - 120 80 - 120 80 - 120 80 - 120 80 - 120 80 - 120 80 - 120 80 - 120

-5.0 -0.20

8888

80 - 120 80 - 120 80 - 120 80 - 120 80 - 120

N N N N

<0.010 40.50 40.20

٥

299192 7299192 299192

Dissolved Manganese (Mn)

7299192 Dissolved Tin (Sn) 7299192 Dissolved Titanium (Ti)

Dissolved Vanadium (V) Dissolved Uranium (U)

2013/11/27 2013/11/27 2013/11/27

80 - 120 80 - 120 80 - 120 80 - 120

N N N N

<0.050 <5.0

80 - 120

å

٩

Dissolved Silicon (Si)
Dissolved Zirconium (Zr)

Dissolved Boron (B) Dissolved Zinc (Zn)

Dissolved Chloride (CI)

Total Antimony (Sb)

8 8 5 1 1 5 5 5

80 - 120 80 - 120 80 - 120 80 - 120

8 4 6 1 6 4 4

80 - 120 80 - 120 80 - 120 80 - 120 80 - 120

40.50

1.0 N N N

<u>^</u>

N N

7299192 Dissolved Strontium (Sr)

Dissolved Selenium (Se) Dissolved Molybdenum (Mo)

2013/11/27

80 - 120 80 - 120 80 - 120 80 - 120

80 - 120 80 - 120 80 - 120 80 - 120

<0.10 <0.020

9

N N N N

<1.0 å

ω ٩ ē ug/L ē ě ξ ٨ ě

2013/11/27

80 - 120

2013/11/27

Dissolved Thaillum (Ti) Dissolved Silver (Ag) Dissolved Nickel (NI) Dissolved Mercury (Hg)

2013/11/27 2013/11/27

7299192 7299192 7299192

Dissolved Cadmium (Cd)

Dissolved Bismuth (Bi)

Dissolved Beryllium (Be) Dissolved Barlum (Ba) Dissolved Antimony (Sb) Total Zirconium (Zr) Total Silicon (SI) Total Boron (B)

2013/1/27 2033/1/127 2033/1/127 2013/1/127 2013/1/127 2013/1/127 2013/1/127 2013/1/127 2013/1/127 2013/1/127 2013/1/127 2013/1/127 2013/1/127

80 - 120

80 - 120

<u>0.10</u>

٩

.30 0.50

<u>0.10</u>

Dissolved Arsenic (As)



Report Date: 2013/11/29

QUALITY ASSURANCE REPORT

Date

%Recovery

QC LImits

Spiked Blank %Recovery QC Limits

Value «50

ē

Value (%)

QC Limits

Method Blank UNITS

<u>^</u>

Matrix Spike

Your P.O. #: S13-5065

City of Parksville



Your P.O. #: S13-5065

City of Parksville

QUALITY ASSURANCE REPORT

			Matrix Spike	Spike	Spiked Blank	Blank	Method Blank	d Blank	RPD	Ď
QC Batch	Parameter	Date	%Recovery QC Limits	QC Limits	% Recovery QC Limits	QC Limits	Value	UNITS	Value (%)	QC Limits
7301221	Total Beryllium (Be)	2013/11/28	103	80 - 120	100	80 - 120	<0.10	ug/L	NC	20
7301221	Total Bismuth (Bil)	2013/11/28	108	80 - 120	97	80 - 120	<1.0	UQ/L	NC	20
7301221	Total Cadmium (Cd)	2013/11/28	109	80 - 120	104	80 - 120	-0.010	ug/L	NC	20
7301221	Total Chromium (Cr)	2013/11/28	110	80 - 120	106	80 - 120	<1.0	ug/L	NC	20
7301221	Total Cobalt (Co)	2013/11/28	107	80 - 120	108	80 - 120	<0.50	ug/L	NC	20
7301221	Total Copper (Cu)	2013/11/28	105	80 - 120	106	80 - 120	<0.20	uq/L	NC	20
7301221	Total Iron (Fe)	2013/11/28	120	80 - 120	118	80 - 120	<5.0	ug/L	NC	20
7301221	Total Lead (Pb)	2013/11/28	99	80 - 120	100	80 - 120	<0.20	ug/L	NC	20
7301221	Total Lithium (LI)	2013/11/28	106	80 - 120	104	80 - 120	·5.0	J/Dn	NC	20
7301221	Total Manganese (Mn)	2013/11/28	109	80 - 120	107	80 - 120	<1.0	ug/L	NC	20
7301221	Total Mercury (Hg)	2013/11/28	99	80 - 120	103	80 - 120	-0.050	uq/L	10000	0.000
7301221	Total Molybdenum (Mo)	2013/11/28	105	80 - 120	102	80 - 120	<1.0	ug/L	NC	20
7301221	Total Nickel (NI)	2013/11/28	108	80 - 120	107	80 - 120	<1.0	ug/L	NC	20
7301221	Total Selenium (Se)	2013/11/28	119	80 - 120	114	80 - 120	<0.10	ug/L	NC	20
7301221	Total Silver (Ag)	2013/11/28	107	80 - 120	98	80 - 120	<0.020	ug/L	NC	20
7301221	Total Strontlum (Sr)	2013/11/28	102	80 - 120	102	80 - 120	<1.0	ug/L	NC	20
7301221	Total Thailium (Ti)	2013/11/28	83	80 - 120	98	80 - 120	<0.050	ug/L	NC	20
7301221	Total Tin (Sn)	2013/11/28	103	80 - 120	103	80 - 120	<5.0	J/Dn	NC	20
7301221	Total Titanium (Ti)	2013/11/28	110	80 - 120	112	80 - 120	-5.0	ug/L	NC	20
7301221	Total Uranium (U)	2013/11/28	96	80 - 120	97	80 - 120	<0.10	ug/L	NC	20
7301221	Total Vanadium (V)	2013/11/28	107	80 - 120	105	80 - 120	<5.0	uq/L	NC	20
7301221	Total Zinc (Zn)	2013/11/28	124(1)	80 - 120	120	80 - 120	<5.0	ug/L	NC	20
7301221	Total Boron (B)	2013/11/28					×50	ug/L	NC	20
7301221	Total Silcon (Si)	2013/11/28	25.5			0	<100	ug/L	NC	20
7301221	Total Zirconium (Zr)	2013/11/28					<0.50	ug/L	NC	20
7301558	Dissolved Chloride (CI)	2013/11/28	97	80 - 120	101	80 - 120	<0.50	mg/L	NC	20

N/A - Not Applicable

RPD - Relative Percent Difference

Duplicate: Paired analysis of a separate portion of the same sample. Used to evaluate the variance in the measurement.

Matrix Spike: A sample to which a known amount of the analyte of interest has been added. Used to evaluate sample matrix interference.

Spiked Blank: A blank matrix sample to which a known amount of the analyte, usually from a second source, has been added. Used to evaluate method accuracy. Method Blank: A blank matrix containing all reagents used in the analytical procedure. Used to identify laboratory contamination.

NC (Matrix Spike): The recovery in the matrix spike was not calculated. The relative difference between the concentration in the parent sample and the spiked amount was not sufficiently significant to permit a reliable recovery calculation. NC (RPD): The RPD was not calculated. The level of analyte detected in the parent sample and its duplicate was not sufficiently significant to permit a reliable calculation.
(1) - Recovery or RPD for this parameter is outside control limits. The overall quality control for this analysis meets acceptability criteria.

- (2) Blank Spike outside acceptance criteria (10% of analytes failure allowed)

Maxxam has procedures in place to guard against improper use of the electronic signature and have the required "signatories", as per section 5.10.2 of ISO/IEC 17015:2005(E), signing the reports. For Service Group specific validation please refer to the Validation Signature Page.



Validation Signature Page

Maxxam Job #: B3A9396

The analytical data and all QC contained in this report were reviewed and validated by the following individual(s)

lidation Coordinator

Water System Operating Conditions



WATER SYSTEM OPERATING CONDITIONS FOR PARKSVILLE, WWS 1116 Herring Gull Way Parksville, BC, V9P 2H3

- Compliance with Operating Permit Terms and Conditions do not relieve the operator of other legislated responsibilities and obligations.
- Water system operators must be familiar with the relevant legislation such as:
 The Drinking Water Protection Act , ([SBC 2001] Chapter 9)
 The Drinking Water Protection Regulation (B.C. Reg. 200/2003 O.C. 508/2003.
- 3. The operator must ensure that the water system is in compliance with any and all lawful direction of the Drinking Water Officer. This includes any correspondence to further explain or alter the above operating terms and conditions. Proposed changes to the operating permit initiated by the Drinking Water Officer will allow an opportunity for input by the water supplier as per section 8 of the Act.

The specific terms and conditions are listed below as:

Condition 1.

The water system owner shall provide a residual level of disinfectant within the water distribution system. It is recommended that the level of residual disinfectant measured at any point within the distribution system be at least 0.20 mg/L, measured as *free* chlorine.

The maximum residual disinfectant concentration, measure as *free* chlorine shall not exceed 4.0 mg/L, or as combined chlorine shall not exceed 3.0 mg/L, anywhere in the distribution system. This does not apply in situations where watermains are being superchlorinated during their installation, repair or routine maintenance.

Condition 2.

Conduct a chemical analysis of raw water from each well in accordance with the list of parameters specified in the VIHA Guidelines for Approval of a Waterworks System at a frequency of no less than once every 5 years.

Health Protection and Environmental Services

Parksville (250) 248-2044 Fax: (250) 248-8624 Part Alberni (250) 724-1281 Fax: (250) 724-4376
Nanaimo (250) 755-6215 Fax: (250) 755-3372 Courtenay (250) 334-5450 Fax: (250) 334-5466

Our Vision: Healthy People, Healthy Island Communities, Seamless Service

Water System Operating Conditions

Condition 3.

Develop and implement a wellhead protection plan to ensure that the drinking water source is protected in to the future. The wellhead protection plan should establish management strategies to avoid contamination of, or activities, which may degrade the quality of the drinking water source. The details of the wellhead protection plan and timing of the implementation of the program shall be established in consultation with the local Environmental Health Officer.

The wellhead protection plan should be based on the publication "Well Protection Tool Kit", Ministry of Environment, Lands and Parks, Ministry of Health and Ministry of Municipal Affairs; Issued by: Water Stewardship Division. ISBN 0-7726-5566-9. http://www.env.gov.bc.ca/wsd/plan protect_sustain/groundwater/wells/well_protection/wellprotect.html

Condition 4.

Develop and implement a Cross-Connection Control Program. The details of the cross-connection program and timing of implementation of the program shall be established in consultation with the local Environmental Health Officer.

Condition 5.

Provide continuous on-line turbidity monitoring of raw water for the Englishman River during drawing periods (May through October as applicable) and ensure the Emergency Response Plan includes appropriate action for turbidity events as detailed in the "Decision Tree for Responding to a Turbidity Event in Unfiltered Drinking Water".

Condition 6.

In accordance with VIHA 4321 treatment policy for the Englishman River water source, provide finished water quality using technology that will achieve the following performance standard; a 4-log removal/inactivation of viruses, a 3-log removal/inactivation of Giardia cysts and Cryptospordium oocysts, provide two treatment processes and produce finished water with less that 1 NTU turbidity.

In consultation with, and in reference to the City of Parksville letter dated February 4, 2009 (Your file 5600-10-AWS), the City of Parksville is required to meet the following implementation plan:

May, 2009: Obtain the services of a professional engineering firm to develop a conceptual plan and preliminary design for a water intake and treatment facility.

November, 2010: Conceptual plan and preliminary design is completed.

<u>December</u>, 2013: Detailed design of the new intake and treatment facility is completed. <u>January</u>, 2015: Construction for the water intake and treatment facility commences with

completion scheduled for December 31, 2016.

Date: Tyrel 2rl 2009